

Liberty Speciality Steel Thrybergh Mill, Rotherham **Collection Plan**



Loading/Securing:

Stand in GREEN area during loading








Minimum 12 Straps LC 2000 daN



MIN X 12 MIN X 24








NOT WORN

LOADS MUST BE SECURED IN THE LOADING BAY – PLEASE HAVE STRAPS READY BEFORE ENTERING THE BAY

3.2 Rectangular and single layer load build

- 2 belly-wrapped straps applied to the middle bundles, maximum 3 bundles within a belly-wrap (see Section 5).
- 3 pairs of opposing loops applied to the whole load.
- False headboard secured with 3 straps.



Cross-sectional view of opposing loop restraint applied to the whole load. Edge protection omitted for clarity.

SECURING INFORMATION WILL BE GIVEN AT POINT OF LOADING