

**Tata Steel Cogent (Orb Electrical Steels)
 Collection Plan**

Loading:

PPE Requirements:

Additional Information:

Monday – Friday
 0600-2000hrs



Reporting/Arrival:



On arrival stop at security gate



Report to weighbridge



Report to drivers reception



Driver will be directed to the loading bay




Driver must stand in safe zone during loading



Loading/Securing:


Stand in green area during loading




Straps LC 2000 daN



NO CUTS




NO KNOTS




NOT WORN



**COIL ON
 PALLET**



FRONT



REAR

FRONT