

Tata Steel Tubes 20" Mill, Hartlepool Collection Plan

Loading:

PPE Requirements:

Monday - Friday 0600-2200 **Booking Slot System**











Additional Information:











Reporting/Arrival:



On arrival stop at weighbridge for tare weight ticket



Park vehicle outside warehouse



Report to drivers reception



When instructed reverse into loading bay

Loading/Securing:

Stand in green area during loading



P&O Ferrymasters

Minimum 12 Straps LC 2000 daN








NOT WORN

LOADS MUST BE SECURED IN THE LOADING BAY - PLEASE HAVE STRAPS READY BEFORE ENTERING THE BAY Loose Tubes excl. 508 diameter

IF USING A FLATBED TRAILER HEADBOARD HEIGHT MUST BE 1.5M

MINIMUM EQUIPMENT REQUIRED:

12 X LC 2000 daN STRAPS 8 X STANCHION POSTS – 4 DOWN EACH SIDE OF 1.5M HIGH, MINIMUM CROSS-SECTION 80 X 80 X 4MM





When 6m tubes loaded, all stanchions should be pulled in by ratchet straps Applied after second row of tubes

